









DE =	EN =	PT =	VN =
Welding symbols			

Welding processes Information 18 Welding Symbols 96_b

Symbolic representation of adhesive, folded and pressed joints (examples)			cf. DIN EN ISO 15785 (2002-12)		
Type of joint	Weld type/ symbol	Meaning/ drawing entry	Type of joint	Weld type/ symbol	Meaning/ drawing entry
Adhesive bonded-seams	Surface seam ¹⁾ 		Folded seam	Folded seam 	
	Stant seam ¹⁾ 		Pressed seam	Pressed seam 	

gezeichnet:	hpw	Datum:		education project	Schweißsymbole	translate/en_ds/p_ct/vn_ro	origin: MT, S. 96
Aenderung:	an	Datum:	08.04.2013	WIAP KFKOK	Welding Symbols	r4a	datei_Wi_8_f_18_d18_r4a_Wel
Aenderung:	control 2	Data:		Safenwil Schweiz	spear 2	www.wiap.ch	idee of / from HPW